17 OCT 2024 AIP SUP 017/2024



REPUBLIC OF LATVIA

Tel: +371 67300664 Fax: +371 67300660 Email: ais@lgs.lv AFS: EVRAYNYX

URL: https://ais.lgs.lv

State Joint-stock Company
"Latvijas gaisa satiksme"
Aeronautical
Information Service
Muzeju iela 3
Lidosta "Rīga"
Mārupes pag., Mārupes nov.
LV-1053, Latvija

AIP SUP 017/2024 Effective from 20 NOV 2024 to 22 JAN 2025 Published on 17 OCT 2024

ATS SURVEILLANCE SERVICES AND PROCEDURES

REF: AIP ENR 1.6.2

The information of this SUP will be incorporated in AIP Latvia with the effective date 23 JAN 2025.

General

When an aircraft carries a serviceable SSR transponder, the pilot shall operate the transponder at all times during flight, regardless of whether the aircraft is within or outside airspace where SSR is used for ATS purposes.

Pilots shall not operate the IDENT feature unless requested by ATS.

Except for flight in airspace for mandatory operation of transponder, aircraft without sufficient electrical power supply are exempted from the requirement to operate the transponder at all times.

When entering the Riga FIR, pilots who have already received specific instructions from ATS unit concerning the setting of the transponder, shall maintain that setting until otherwise instructed.

Except specific contingency situation, pilots shall:

- select codes as instructed by the ATS unit; or
- in the absence of ATS instructions related to code setting, select Mode A code 2000; or
- when not receiving air traffic services, select Mode A code 7000 in order to improve the detection of suitably equipped aircraft.

1. Emergency procedures

The pilot of an aircraft equipped with SSR shall select Mode A Code 7700 to indicate a state of emergency unless ATC has previously directed the pilot to operate the transponder on a specified code. In the latter case, a pilot may nevertheless select Mode A Code 7700 whenever there is a specific reason to believe that this would be the best course of action.

Note: Mode A Code 7700 is permanently monitored in the Riga FIR.

2. Air-ground communication failure and unlawful interference procedures

2.1 Radio communication failure procedure

In the event of a radio communication failure, Mode A code 7600 shall be selected. Applicable radio communication failure procedures are to be followed.

Note: Mode A Code 7600 is permanently monitored in the Riga FIR.

2.2 Unlawful interference procedure

AIP SUP 017/2024 17 OCT 2024

The pilot of an aircraft which is subjected to unlawful interference shall attempt to select Mode A Code 7500 to provide an indication of a state of unlawful interference. If circumstances so warrant, Mode A Code 7700 should be used instead.

Note: Mode A Code 7500 is permanently monitored in the Riga FIR.

3. System of SSR code assignment

SSR codes used for IFR flights in Riga FIR are assigned and managed by European Centralised SSR Code Assignment and Management System (CCAMS).

SSR codes used for VFR flights in Riga FIR are assigned and managed by ATS unit according to the SSR Code Allocation List.