



REPUBLIC OF LATVIA

Phone: +371 67300664
Fax: +371 67300660
Email: ais@lgs.lv
AFS: EVRAYNYX
URL: <https://ais.lgs.lv>

State Joint-stock Company
"Latvijas gaisa satiksme"
Aeronautical Information Service
Muzeju iela 3, Lidosta "Rīga"
Mārupes novads, LV-1053, Latvija

AIP SUP: 007/2021
Effective Date: 09-APR-2021
End date: 16-JUN-2021
Publication Date: 09-APR-2021

RIGA AERODROME (EVRA) - CHANGES TO AERODROME ACCEPTED DEVIATIONS FROM THE APPLICABLE REQUIREMENTS

REF: AIP EVRA AD 2.23

The information will be incorporated in AIP Latvia WEF 17 JUN 2021.

EVRA AD 2.23 ADDITIONAL INFORMATION

4. Aerodrome accepted deviations from the applicable requirements and special conditions

4.1 Deviations

The following deviations are withdrawn:

Applicable requirement	Deviation description
CS ADR-DSN.B.130 Slopes on runway shoulders	Full-fledged drainage is not provided on a runway shoulder and the transverse slope of a surface of the runway shoulder locally around the drainage gullies exceeds 2.5%.
CS ADR-DSN.B.145 Surface of runway shoulders	The surface of the runway shoulder is not resistant to erosion.

The following deviation description is updated:

Applicable requirement	Deviation description
CS ADR-DSN.M.750 Apron floodlighting	On aprons 2 and 4 the average illuminance on taxilines C, P and E1 does not reach 50% of the average illuminance of the aircraft parking areas.

THIS PAGE INTENTIONALLY LEFT